
Little Tokyo Village Ped Lights (see photo #9)
2.87Fc
2.50Fc
Under soffit lights at the store front. (see photo #8)
2ND STREET
SAN PEDRO STREET
AZUSA STREET
8
10
11
12
1
MH?
Existing 3-headed pole: (1) lamp out (see photo #7)
wall pack on roof level building exterior, observed to be metal halide (see photo #3)
1.52Fc
0.94Fc
3.34Fc
2.05Fc
7.05Fc
7.99Fc
5.00Fc
28.91Fc
LED
5.60Fc
(2) HPS wall packs at ground level (see photo #6)
Dark Elevator Tower
1.46Fc
Existing 3-headed pole: (3) lamps out (see photo #5)
2.60Fc
1.55Fc
0.86Fc
2.05Fc
Business Closed
A continuous row of linear fluorescent at the top of the wall towards JACCC (see photo #1& #2)
4756K LED wall packs (see photo #2)
JACCC Building:
Dark Windows + Glary Wall Packs on Top of the Building Facade
Existing 3-headed pole: (2) lamps out (see photo #4)
LIGHTING DESIGN ALLIANCE

1

2

3

4

5

6

7

8

9

10

11

12